

BLAST REPORT

BLAST REPORT # WS11☐ Sanders Construction, Inc.☒ Western States Drilling & Blasting, Inc.DATE: JULY 26, 2010EXACT TIME OF SHOT: 8:07 PMCUSTOMER: KLBJOB NO.: WS21005SHOT LOCATION WITH GPS COORDINATES: Sta 1317+55 - 1318+175 TICKET NO.: _____CHECK LIST COMPLETED: ☒ YES ☐ NO

TYPE OF ROCK: BASALT FACE HEIGHT: N/A FT. POUNDS PER DELAY: _____

TOTAL HOLES: 22

NUMBER OF HOLES: 22 HOLE DIA: 3 3/4" BxS 30" x _____ STEMMING: 5' DEPTH: 31'-33'

NUMBER OF HOLES: 707 TOTAL FT DRILLED HOLE DIA: _____ BxS _____ x _____ STEMMING: _____ DEPTH: _____

POWDER FACTOR: NA LBS. OF EXPLOSIVES: _____ YARDS OF ROCK: NA

WEATHER: _____ WIND: _____

EXACT MONITOR LOCATION(GPS): NA DIRECTION OF BLAST: _____ MONITOR TYPE: _____

MONITOR: L/R _____ T _____ V _____ PVS _____ Db _____ MONITOR SERIAL NO.: _____

DISTANCE TO BLAST: _____ AVERAGE POUNDS PER HOLE: _____ OPERATOR: _____

EXACT MONITOR LOCATION(GPS): _____ DIRECTION OF BLAST: _____ MONITOR TYPE: _____

MONITOR: L/R _____ T _____ V _____ PVS _____ Db _____ MONITOR SERIAL NO.: _____

DISTANCE TO BLAST: _____ AVERAGE POUNDS PER HOLE: _____ OPERATOR: _____

EXPLOSIVES

DESCRIPTION	QUANTITY USED	DATE CODE	MAGAZINE	REMOVED	RETURNED
LOCATION:					
BULK A/N	Lbs				
BAG ANFO	Bags				
POWDER <u>SHURETUB</u>	<u>207#</u> ea.	<u>0091119</u>			
POWDER	ea.				
lb. BOOSTER	ea.				
lb. BOOSTER	ea.				
<u>12</u> ft. <u>TD9</u>	<u>6</u> ea.	<u>31MY04B4</u>			
ft.	ea.				
ft.	ea.				
ft.	ea.				
ft.	ea.				
ft.	ea.				
ft.	ea.				
ft. ms	ea.				
	ft.				
<u>25</u> GRAIN CORD	<u>60'</u> ft.	<u>290C07T4</u>			
<u>50</u> GRAIN CORD	<u>170'</u> ft.	<u>09N009T4</u>			
MISCELLANEOUS					
<u>LIL</u>	<u>1000'</u>	<u>05AP10B4</u>			



COMMENTS: FAIRLY SIGNIFICANT VERTICAL MOVEMENT & DISPLACEMENT. ROCK SEEMS VERY WEAK & FRAGMENTED.

BLASTER'S SIGNATURE: Chen ShuLICENSE NO.: U212 62

Revised 03/04

ATTACH SKETCH OF SHOT

THIS FORM MUST BE FILLED OUT COMPLETELY



PROPOSED 540T #W511
PROPOSED DATE: JULY 26, 2010

Western States Drilling Blasting Drill Log

Shot #: US 11

Date: 7-22-10

Drill #

Driller Name

Buck

0.5:1 slope

87° 6' 6"

2 1/2" / 3 1/2"

Hole #	P=Production S=Presplit E=Explore B=Bolders	Depth Drilled	Depth to Rock	Voids at What Depth	Notes W=Water
1	S	31	31'		1317+75 4' dirt 27' soft rock
2	S	31	32'	6'	20' soft rock 2' brown 4' hard rock
3		31	32'	6'	" "
4		31	32'	6'	" "
5		31	32'	6'	" "
6		31	32'	6'	" "
7		32	32'	7'	6' soft rock 2' brown dirt 17' soft rock
8		32	32'	7'	" "
9		32	32'	7'	" "
10		33	33'	7'	" "
11		33	33'	7'	6W 1318+00 "
12		33	33'	5'	16' soft rock 3' dirt
13		33	33'	7'	20' hard rock 6' soft red rock
14		33	33'	10'	13' hard rock 10' red soft rock
15		33	33'	7'	17' hard rock 3' red soft roc 3' hard
16		33	34'	7'	" "
17		33	33'	7'	" "
18		33	33'	7'	" "
19		32	33'	7'	" "
20		32	32'	6'	
21	S	32	32'	5'	
22	S	32	32'	6'	1318+25
23					
24					
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					

7-21-10
↑
W

7-22-10

707 LF
TOTAL

Presplit

Check List

Job Number

WS00015

Date

July 26, 2010

Shot Number

WS 11

1. BEFORE BLASTING

NOTIFICATION

- ☒ Fire Department
- ☒ Utilities
- ☒ Businesses & Home Owners
- ☒ Seismograph Tech
- ☒ Other (List)

MATERIAL & EQUIPMENT

- ☒ Adequate Stemming Material
- ☒ Warning Signs
- ☒ Warning Signals
- ☒ Safe Amount of Lead Line
- ☒ Seismograph Paper, Pens, etc.
- ☒ Fire Extinguishers (charged)
- ☒ Adequate Blasting Shelter
- ☒ Mats (If Applicable)

SHOT DESIGN

- ☒ Pattern OK for Area
- ☒ Sufficient Burden to Face
- ☒ Reviewed drill logs
- ☒ Measured Depth, Burden & Spacing
- ☒ Shot Area Posted & Secure
- ☒ Shot Diagramed on Back

2. DURING LOADING

CONSTANT CHECKS

- ☒ Explosives
- ☒ Running Inventory
- ☒ Access Row Empty
- ☒ Drills & Traffic 50' Away
- ☒ Shot can be fired in case of emergency
- All Holes to be checked & approved
- ☒ Blaster initial
- ☒ Supt initial

3. DETONATION

HOOK - UP

- ☒ All Unnecessary Crew Cleared
- ☒ All Holes Loaded & Stemmed
- ☒ Hand Check tubing Before Each Connection
- ☒ Visually Insured That Each Connection is Snapped

SECURE AREA

- ☒ Set up Seismograph
- ☒ Est. Checkpoints at Each Access
- ☒ Radio Communication with Checkpoints.
- ☒ Cleared People, Vehicles & Equipment
- ☒ Visual Coverage of Entire Site
- ☒ Five Minute Warning
- ☒ One Minute Warning

4. AFTER DETONATION

POST BLAST CHECK

- ☒ Waited for Dust & Fumes to Dissipate
- ☒ Walked Entire Area of Shot
- ☒ Insured that tail Surface Delays Fired at the End of Each Row
- ☒ Sounded All Clear Signal

LEGAL DOCUMENTATION

- ☒ Completed Shot Report
- ☒ Diagramed Shot w/ Seismograph Location (Direction & Distance)
- ☒ Recorded Seismic Results on Blast Report
- ☒ Final Inventory of Explosives Recorded
- ☒ Ticket Number Assigned By Job Supervisor
- ☒ Signed Blast Report w/ License No.

Supt has checked and verified that all has been completed and shot area is ready for loading

CAH

Supt initial